

# ISO/TS 24110:2026-04 (E)

## Plastics - Method of exposure to combined UV radiation and creep load

---

### Contents

Page

Foreword.....	iv
Introduction.....	v
<b>1 Scope.....</b>	<b>1</b>
<b>2 Normative references.....</b>	<b>1</b>
<b>3 Terms and definitions.....</b>	<b>1</b>
<b>4 Principle.....</b>	<b>2</b>
<b>5 Apparatus.....</b>	<b>2</b>
5.1 General.....	2
5.2 Test device for combined exposure.....	2
5.3 Laboratory UV radiation source.....	2
5.3.1 General.....	2
5.3.2 Fluorescent UVA lamp.....	2
5.3.3 Fluorescent UVB lamp.....	2
5.3.4 Low pressure mercury UVC lamp.....	2
5.4 Radiometer.....	2
5.5 Black-panel/black-standard thermometer.....	2
5.6 Creep device.....	3
5.6.1 General.....	3
5.6.2 Loading system.....	3
5.6.3 Specimen grip.....	3
5.7 Assessment of changes in properties.....	3
<b>6 Test specimens.....</b>	<b>3</b>
<b>7 Test conditions for combined exposure.....</b>	<b>3</b>
<b>8 Procedure.....</b>	<b>4</b>
8.1 General.....	4
8.2 Mounting of the test specimen.....	4
8.3 Combined exposure.....	5
8.3.1 Conditioning.....	5
8.3.2 Preloading.....	5
8.3.3 Loading.....	5
8.3.4 UV exposure.....	5
8.4 Extension measurement schedule.....	5
8.5 Time measurement for creep.....	5
8.6 Measurement of radiant exposure.....	5
8.7 Determination of the changes in properties after exposure.....	5
<b>9 Test report.....</b>	<b>5</b>
<b>Annex A (informative) Comparison of UV exposure and combined creep 10 %, 20 %, 30 % creep load based on tensile yield strength.....</b>	<b>7</b>
<b>Annex B (informative) Combined UV radiation and creep load test equipment.....</b>	<b>10</b>