

DIN EN 15622:2010-06 (E)

Copper and copper alloys - Determination of lead content - Flame atomic absorption spectrometric method (FAAS)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	5
6	Sampling	5
7	Procedure	5
7.1	Preparation of the test portion solution	5
7.1.1	Test portion	5
7.1.2	Test portion solution	5
7.1.3	Lead mass fractions between 0,01 % and 0,15 %	6
7.1.4	Lead mass fractions between 0,1 % and 0,75 %	6
7.1.5	Lead mass fractions between 0,5 % and 5,0 %	6
7.2	Blank test	6
7.3	Check test	6
7.4	Establishment of the calibration curve	6
7.4.1	Preparation of the calibration solutions	6
7.4.2	Adjustment of the atomic absorption spectrometer	8
7.4.3	Spectrometric measurement	8
7.4.4	Calibration curve	8
7.5	Determination	8
7.5.1	General	8
7.5.2	Preliminary spectrometric measurement	9
7.5.3	Spectrometric measurements	9
8	Expression of results	9
8.1	Use of calibration curve	9
8.2	Use of bracketing method	9
9	Precision	10
10	Test report	11
Bibliography		12