

# DIN EN 15023-3:2010-12 (E)

## Copper and copper alloys - Determination of nickel content - Part 3: Flame atomic absorption spectrometric method (FAAS)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Principle .....	4
4	Reagents .....	4
5	Apparatus .....	5
6	Sampling .....	5
7	Procedure .....	5
7.1	Preparation of the test portion solution .....	5
7.1.1	General .....	5
7.1.2	Nickel mass fractions between 0,001 % and 0,012 5 % .....	6
7.1.3	Nickel mass fractions between 0,01 % and 0,25 % .....	6
7.1.4	Nickel mass fractions between 0,2 % and 6,0 % .....	6
7.2	Blank test .....	6
7.3	Check test .....	6
7.4	Establishment of the calibration curve .....	7
7.4.1	Preparation of the calibration solutions .....	7
7.4.2	Adjustment of the atomic absorption spectrometer .....	9
7.4.3	Spectrometric measurement of the calibration solutions .....	9
7.4.4	Calibration curve .....	9
7.5	Determination .....	9
7.5.1	General .....	9
7.5.2	Preliminary spectrometric measurement .....	9
7.5.3	Spectrometric measurements .....	9
8	Expression of results .....	10
8.1	Use of calibration curve .....	10
8.2	Use of bracketing method .....	10
9	Precision .....	11
10	Test report .....	12
Bibliography .....		13