

DIN EN 15023-3:2010-12 (E)

Copper and copper alloys - Determination of nickel content - Part 3: Flame atomic absorption spectrometric method (FAAS)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	5
6	Sampling	5
7	Procedure	5
7.1	Preparation of the test portion solution	5
7.1.1	General	5
7.1.2	Nickel mass fractions between 0,001 % and 0,012 5 %	6
7.1.3	Nickel mass fractions between 0,01 % and 0,25 %	6
7.1.4	Nickel mass fractions between 0,2 % and 6,0 %	6
7.2	Blank test	6
7.3	Check test	6
7.4	Establishment of the calibration curve	7
7.4.1	Preparation of the calibration solutions	7
7.4.2	Adjustment of the atomic absorption spectrometer	9
7.4.3	Spectrometric measurement of the calibration solutions	9
7.4.4	Calibration curve	9
7.5	Determination	9
7.5.1	General	9
7.5.2	Preliminary spectrometric measurement	9
7.5.3	Spectrometric measurements	9
8	Expression of results	10
8.1	Use of calibration curve	10
8.2	Use of bracketing method	10
9	Precision	11
10	Test report	12
Bibliography		13