

DIN EN 15063-1:2015-03 (E)

Copper and copper alloys - Determination of main constituents and impurities by wavelength dispersive X-ray fluorescence spectrometry (XRF) - Part 1: Guidelines to the routine method

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Principle	5
3	Terms and definitions	5
4	Instrumentation	7
4.1	Principles of X-ray fluorescence spectrometers	7
4.2	X-ray tubes	8
4.3	Vacuum system	9
4.4	Test sample spinner	9
4.5	Filters	9
4.6	Collimators of slits	10
4.7	Analysing crystals	10
4.8	Counters	11
4.9	Simultaneous and sequential Instruments	12
5	Sampling and test sample preparation	12
6	Evaluation methods	12
6.1	General	12
6.2	Dead time correction	12
6.3	Background correction	13
6.4	Line interference correction models	13
6.5	Inter-element effects correction models	13
7	Calibration procedure	14
7.1	General	14
7.2	Optimizing of the diffraction angle (2)	15
7.3	Selecting optimum conditions for detectors	15
7.4	Selecting optimum tube voltage and current	15
7.5	Selecting minimum measuring times	15
7.6	Selecting calibration samples	15
7.7	Selecting drift control and recalibration samples	16
7.8	Measuring the calibration samples	16
7.9	Regression calculations	16
8	Method validation (accuracy and precision)	16
9	Performance criteria	17
9.1	General	17
9.2	Precision test	17
9.3	Performance monitoring	17
9.4	Maintenance	17

10	Radiation protection	18
	Annex A (informative) Example of calculating background equivalent concentration, limit of detection, limit of quantification and lower limit of detection	19
	Annex B (informative) Example of calculating line interference of one element to another	21
	Annex C (informative) Example of performance criteria obtained under repeatability conditions	22
	Bibliography	23