

# ISO 12743:2018 (E)

## Copper, lead, zinc and nickel concentrates — Sampling procedures for determination of metal and moisture content

---

### Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Sampling theory
4.1	General
4.2	Total variance
4.3	Sampling-stage method of estimating sampling and total variance
4.4	Simplified method of estimating sampling and total variance
4.5	Interleaved sample method of measuring total variance
5	Establishing a sampling scheme
6	Mass of increment
6.1	General
6.2	Mass of increment for falling-stream samplers
6.3	Mass of increment for cross-belt samplers
6.4	Mass of increment for manual sampling from stationary lots
6.4.1	Primary increments
6.4.2	Mass of secondary and subsequent increments
6.5	Mass of increment for stopped-belt reference sampling
7	Methods of sampling from concentrate streams
7.1	General
7.2	Mass-basis systematic sampling
7.2.1	General
7.2.2	Sampling interval
7.2.3	Sample cutter
7.2.4	Taking of primary increments
7.2.5	Constitution of subsamples and lot samples
7.2.6	Types of division
7.2.7	Division of increments
7.2.8	Division of subsamples
7.2.9	Division of lot samples
7.3	Time-basis systematic sampling
7.3.1	General
7.3.2	Sampling interval
7.3.3	Sample cutter
7.3.4	Taking of primary increments
7.3.5	Constitution of subsamples and lot samples
7.3.6	Types of division
7.3.7	Division of increments and subsamples
7.3.8	Division of lot samples
7.4	Stratified random sampling
7.4.1	Fixed mass intervals
7.4.2	Fixed time intervals
8	Mechanical sampling of concentrate streams
8.1	General

- 8.2 Design of the sampling system
  - 8.2.1 Safety of operators
  - 8.2.2 Location of sample cutters
  - 8.2.3 Provision for interleaved sampling
  - 8.2.4 Provision for stratified random sampling
  - 8.2.5 Checking precision and bias
  - 8.2.6 Avoiding bias
  - 8.2.7 Minimizing bias
  - 8.2.8 Configuration of the sampling system
- 8.3 Sample cutters
  - 8.3.1 General
  - 8.3.2 Design criteria
    - 8.3.2.1 General
    - 8.3.2.2 Falling-stream cutters
    - 8.3.2.3 Cross-belt cutters
  - 8.3.3 Cutter speed
    - 8.3.3.1 General
    - 8.3.3.2 Falling-stream cutters
    - 8.3.3.3 Cross-belt cutters
- 8.4 Mass of increments
- 8.5 Number of increments
- 8.6 Sampling interval
- 8.7 Routine checking
- 9 Manual sampling of concentrate streams
  - 9.1 General
  - 9.2 Choosing the sampling location
  - 9.3 Sampling implements
  - 9.4 Mass of increments
  - 9.5 Number of increments
  - 9.6 Sampling interval
  - 9.7 Sampling procedures
    - 9.7.1 General
    - 9.7.2 Full stream cut from a falling stream
    - 9.7.3 Partial stream cuts from a falling stream
    - 9.7.4 Sampling from moving conveyor belts
- 10 Stopped-belt reference sampling
- 11 Sampling from grabs
  - 11.1 General
  - 11.2 Mass of primary increments
  - 11.3 Number of primary increments
  - 11.4 Method of sampling
  - 11.5 Constitution of subsamples and lot samples
- 12 Sampling from trucks, railway wagons and sampling hoppers
  - 12.1 General
  - 12.2 Mass of primary increments
  - 12.3 Number of primary increments
  - 12.4 Method of sampling
  - 12.5 Constitution of subsamples and lot samples
- 13 Sampling of concentrate in bags or drums
  - 13.1 General
  - 13.2 Mass of primary increments
  - 13.3 Number of primary increments
  - 13.4 Method of sampling
    - 13.4.1 General
    - 13.4.2 Sampling during filling or emptying
    - 13.4.3 Spear sampling
  - 13.5 Constitution of subsamples and lot samples
- 14 Sampling of stockpiles

**15 Methods of comminution, mixing and division**

- 15.1 General**
- 15.2 Comminution**
  - 15.2.1 General**
  - 15.2.2 Mills**
- 15.3 Mixing**
  - 15.3.1 General**
  - 15.3.2 Methods of mixing**
- 15.4 Division**
  - 15.4.1 Chemical analysis samples**
  - 15.4.2 Moisture samples**
  - 15.4.3 Number of increments for division**
  - 15.4.4 Minimum mass of divided sample**
  - 15.4.5 Rotary sample division**
  - 15.4.6 Cutter-type division**
  - 15.4.7 Manual increment division**
  - 15.4.8 Spear division**
  - 15.4.9 Fractional shovelling**
  - 15.4.10 Ribbon division**
  - 15.4.11 Riffle division**

**16 Sample requirements**

- 16.1 Moisture samples**
  - 16.1.1 Mass of test portion**
  - 16.1.2 Processing of samples**
- 16.2 Chemical analysis samples**
- 16.3 Physical test samples**

**17 Packing and marking of samples**

**Annex A (normative) Sampling stage method of estimating sampling and total variance**

- A.1 Components of sampling error and sampling variance**
- A.2 Estimation of fundamental variance**
- A.3 Segregation and grouping variance**
- A.4 Long-range quality fluctuation variance**
- A.5 Practical estimation of total variance**

**Annex B (informative) Estimation of total variance — Barge unloading using a grab**

- B.1 Definition of example**
- B.2 Estimation of total variance**
  - B.2.1 Determination of mass fraction of metal**
  - B.2.2 Determination of moisture content**
- B.3 Summary**

**Annex C (informative) Mechanical sample cutters**

- C.1 Scope**
- C.2 Types of mechanical sample cutters**

**Annex D (informative) Checklist for mechanical sampling systems**

**Annex E (normative) Manual sampling devices**

- E.1 Scope**
- E.2 Manual cutters**
- E.3 Sampling scoops**

**Annex F (informative) Apparatus for manual sampling of concentrates from stopped belts**

**Annex G (informative) Sampling of stockpiles**

- G.1 General**
- G.2 Selection of sampling points**
- G.3 Mass of primary increments**
- G.4 Number of primary increments**
- G.5 Sampling procedure**

**G.6 Constitution of lot samples or subsamples**

**Annex H (normative) Increment division scoops for conducting manual increment division**

**Page count: 79**