

DIN EN 15024-2:2007-01 (E)

Copper and copper alloys - Determination of zinc content - Part 2: Flame atomic absorption spectrometry method (FAAS)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents and materials	4
5	Apparatus	5
6	Sampling	5
7	Procedure	6
8	Expression of results	11
9	Precision	12
10	Test report	13
Bibliography		14