

# DIN EN 15063-1:2007-01 (E)

## Copper and copper alloys - Determination of main constituents and impurities by wavelength dispersive X-ray fluorescence spectrometry (XRF) - Part 1: Guidelines to the routine method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Principle .....	5
3	Terms and definitions .....	5
4	Instrumentation .....	7
5	Sampling and test sample preparation .....	12
6	Evaluation methods .....	12
7	Calibration strategy .....	15
8	Method validation (accuracy and precision) .....	17
9	Performance criteria .....	17
10	Radiation protection .....	18
Annex A (informative) Example of calculating background equivalent concentration, limit of detection, limit of quantification and lower limit of detection .....		19
Annex B (informative) Example of calculating line interference of one element to another .....		21
Annex C (informative) Example of performance criteria obtained in a precision test .....		22
Bibliography .....		23