

# ISO 6106:2013-04 (E)

## Abrasive products - Checking the grain size of superabrasives

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Apparatus .....</b>	<b>1</b>
4.1	Sieving machine .....	1
4.2	Sieves .....	1
4.3	Sampling the batch .....	2
4.4	Balance .....	2
4.5	Timer .....	2
<b>5</b>	<b>Test conditions .....</b>	<b>3</b>
<b>6</b>	<b>Test sieving .....</b>	<b>3</b>
6.1	Sampling .....	3
6.2	Preparation for sieving .....	3
6.3	Sieving procedure .....	3
<b>7</b>	<b>Evaluation .....</b>	<b>3</b>
7.1	Weighing sieved fractions .....	3
7.2	Calculation of results .....	3
<b>8</b>	<b>Designation and grading limits .....</b>	<b>4</b>
8.1	General .....	4
8.2	Grain sizes .....	4
8.3	Designation .....	4
<b>9</b>	<b>Example showing the use of Table 2 .....</b>	<b>4</b>
<b>Annex A (normative) Adaptors for 75 mm sieves .....</b>		<b>7</b>
<b>Bibliography .....</b>		<b>9</b>