

ISO/TS 13399-311:2016-03 (E)

Cutting tool data representation and exchange - Part 311: Creation and exchange of 3D models - Solid reamers

Contents		Page
Foreword		v
Introduction		vii
1	Scope	1
2	Normative references	1
3	Starting elements, coordinate systems, planes	2
3.1	General	2
3.2	Reference system	2
3.3	Primary coordinate system and mounting coordinate system	2
3.4	Coordinate system at the cutting part	3
3.5	Planes	4
3.6	Cutting reference point	5
4	Design of the model	5
4.1	General	5
4.2	Necessary properties for the connection interface feature	6
5	Cylindrical reamer	6
5.1	General	6
5.2	Necessary properties	7
5.3	Geometry of the non-cutting part including the connection	7
5.4	Geometry of the cutting part	8
5.5	Complete cylindrical reamer	9
6	Tapered reamer	9
6.1	General	9
6.2	Necessary properties	10
6.3	Geometry of the non-cutting part including the connection	10
6.4	Geometry of the cutting part	10
6.5	Complete tapered reamer	11
7	Stepped reamer	11
7.1	General	11
7.2	Necessary properties	12
7.3	Geometry of the non-cutting part including the connection	13
7.4	Geometry of the cutting part	13
7.5	Complete stepped reamer	14
8	Bell-style reamer	14
8.1	General	14
8.2	Necessary properties	15
8.3	Geometry of the non-cutting part including the connection	16
8.4	Geometry of the cutting part	16
8.5	Complete bell-style reamer	17
9	Shell reamer	17
9.1	General	17
9.2	Necessary properties	18

9.3	Geometry of the non-cutting part including the connection	18
9.4	Geometry of the cutting part	19
9.5	Complete shell reamer	20
10	Design of details	21
10.1	Basics for modelling	21
10.2	Contact/clamping surfaces -- Orientation	21
10.3	Chamfers and roundings	21
11	Attributes of surfaces -- Visualization of the model features	21
12	Structure of the design elements (tree of model)	21
13	Data exchange model	22
Annex A (informative) Information about nominal dimensions		23
Bibliography		24