

# ISO 3002-1:1982-08 (E)

Basic quantities in cutting and grinding; Part 1 : Geometry of the active part of cutting tools; General terms, reference systems, tool and working angles, chip breakers

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope and field of application .....</b>	<b>1</b>
<b>2</b>	<b>Reference .....</b>	<b>1</b>
<b>3</b>	<b>General terms .....</b>	<b>1</b>
<b>3.1</b>	<b>Surfaces on the workpiece .....</b>	<b>1</b>
<b>3.2</b>	<b>Tool elements .....</b>	<b>1</b>
<b>3.3</b>	<b>Tool surfaces .....</b>	<b>1</b>
<b>3.4</b>	<b>Cutting edges .....</b>	<b>2</b>
<b>3.5</b>	<b>Dimensions .....</b>	<b>3</b>
<b>3.6</b>	<b>Tool and workpiece motions .....</b>	<b>8</b>
<b>4</b>	<b>Reference systems .....</b>	<b>12</b>
<b>4.1</b>	<b>Tool-in-hand system .....</b>	<b>12</b>
<b>4.2</b>	<b>Tool-in-use system .....</b>	<b>19</b>
<b>5</b>	<b>Tool and working angles .....</b>	<b>26</b>
<b>5.1</b>	<b>Tool angles .....</b>	<b>26</b>
<b>5.2</b>	<b>Working angles .....</b>	<b>33</b>
<b>5.3</b>	<b>Sign Convention for angles .....</b>	<b>38</b>
<b>6</b>	<b>Summary of angles .....</b>	<b>39</b>
<b>7</b>	<b>Chip breaker .....</b>	<b>42</b>
<b>Annex : Lists of equivalent terms in French, Russian, German, Italian and Dutch.....</b>		<b>46</b>