

ISO 22262-1:2012-07 (E)

Air quality - Bulk materials - Part 1: Sampling and qualitative determination of asbestos in commercial bulk materials

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Terms and definitions	1
3	Symbols and abbreviated terms	7
4	Principle	8
4.1	General	8
4.2	Substance determination	8
4.3	Type of sample	8
4.4	Range	8
4.5	Limit of detection	9
4.6	Limitations of PLM in the detection of asbestos	9
5	Sample collection	9
5.1	Requirements	9
5.2	Procedure	10
6	Sample preparation	14
6.1	General	14
6.2	Removal of organic materials by ashing	14
6.3	Removal of soluble constituents by acid treatment	14
6.4	Sedimentation and flotation	14
6.5	Combination of gravimetric reduction procedures	14
7	Analysis by PLM	14
7.1	Requirements	14
7.2	Qualitative analysis by PLM	19
8	Analysis by SEM	29
8.1	General	29
8.2	Requirements	29
8.3	Calibration	29
8.4	Sample preparation	30
8.5	Qualitative analysis by SEM	30
9	Analysis by transmission electron microscope	31
9.1	General	31
9.2	Requirements	32
9.3	Calibration	32
9.4	Sample preparation	33
9.5	Qualitative analysis by TEM	33
10	Test report	35
Annex A (normative)	Types of commercial asbestos-containing material	36

Annex B (normative) Interference colour chart	40
Annex C (normative) Dispersion staining charts	41
Annex D (normative)AsbestosidentificationbyPLManddispersionstainingin commercial materials ..	43
Annex E (normative)AsbestosidentificationbySEMIncommercialmaterials	52
Annex F (normative)AsbestosidentificationbyTEMIncommercialmaterials	58
Annex G (informative) Example of sampling record	67
Annex H (informative) Example of test report	68
Bibliography	69