

# ISO 10312:2019-10 (E)

## Ambient air - Determination of asbestos fibres - Direct transfer transmission electron microscop y method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	5
5	Type of sample .....	6
6	Range .....	6
7	Limit of detection .....	6
8	Principle .....	7
9	Reagents .....	7
10	Apparatus .....	8
10.1	Air sampling -- Equipment and consumable supplies .....	8
10.1.1	Filter cassette .....	8
10.1.2	Sampling pump .....	8
10.1.3	Stand .....	8
10.1.4	Personal sampling .....	8
10.1.5	Flowmeter .....	8
10.2	Specimen preparation laboratory .....	9
10.3	Equipment for analysis .....	9
10.3.1	Transmission electron microscope .....	9
10.3.2	Energy dispersive X-ray analyser .....	11
10.3.3	Plasma asher .....	11
10.3.4	Vacuum coating unit .....	11
10.3.5	Sputter coater .....	11
10.3.6	Solvent washer (Jaffe washer) .....	11
10.3.7	Condensation washer .....	12
10.3.8	Slide warmer or oven .....	13
10.3.9	Ultrasonic bath .....	13
10.3.10	Carbon grating replica .....	13
10.3.11	Calibration specimen grids for EDXA .....	13
10.3.12	Carbon rod sharpener .....	14
10.3.13	Disposable tip micropipettes .....	14
10.4	Consumable supplies .....	14
10.4.1	Copper or nickel electron microscope grids .....	14
10.4.2	Gold or nickel electron microscope grids .....	14
10.4.3	Carbon rod electrodes .....	14
10.4.4	Routine electron microscopy tools and supplies .....	14
10.4.5	Reference asbestos samples .....	14
10.4.6	Reference samples of mineral fibres other than asbestos .....	15

11	Air sample collection .....	15
12	Procedure for analysis .....	16
12.1	General .....	16
12.2	Cleaning of sample cassettes .....	16
12.3	Direct preparation of TEM specimens from polycarbonate filters .....	17
12.3.1	Selection of filter area for carbon coating .....	17
12.3.2	Carbon coating of filter portions .....	17
12.3.3	Preparation of the Jaffe washer .....	17
12.3.4	Placing of specimens in the Jaffe washer .....	17
12.4	Direct preparation of TEM specimens from cellulose ester filters .....	18
12.4.1	Selection of area of filter for preparation .....	18
12.4.2	Preparation of solution for collapsing cellulose ester filters .....	18
12.4.3	Filter collapsing procedure .....	18
12.4.4	Plasma etching of the filter surfaces .....	18
12.4.5	Carbon coating .....	18
12.4.6	Preparation of the Jaffe washer .....	18
12.4.7	Placing of specimens in the Jaffe washer .....	18
12.5	Criteria for acceptable TEM specimen grids .....	19
12.6	Procedure for structure counting by TEM .....	19
12.6.1	General .....	19
12.6.2	Measurement of mean opening area .....	20
12.6.3	TEM alignment and calibration procedures .....	20
12.6.4	Determination of criterion for termination of TEM examination .....	20
12.6.5	General procedure for structure counting and size analysis .....	21
12.6.6	Magnification requirements .....	23
12.7	Blank and quality control determinations .....	24
12.8	Calculation of results .....	24
13	Performance characteristics .....	25
13.1	General .....	25
13.2	Interferences and limitations of fibre identification .....	25
13.3	Precision and accuracy .....	25
13.3.1	Precision .....	25
13.3.2	Accuracy .....	26
13.3.3	Inter-laboratory and intra-laboratory analyses .....	26
13.4	Limit of detection .....	26
14	Test report .....	27
	Annex A (normative) Determination of operating conditions for plasma asher .....	30
	Annex B (normative) Calibration procedures .....	31
	Annex C (normative) Structure counting criteria .....	34
	Annex D (normative) Fibre identification procedure .....	44
	Annex E (normative) Determination of the concentration of asbestos fibres and bundles longer than 5 µm, and PCM equivalent asbestos fibres .....	61
	Annex F (normative) Calculation of results .....	62
	Annex G (informative) Strategies for collection of air samples .....	68
	Annex H (informative) Methods for removal of gypsum fibres .....	69
	Bibliography .....	70