

DIN EN 15267-4:2024-09 (E)

Air quality - Assessment of air quality monitoring equipment - Part 4: Performance criteria and test procedures for portable automated measuring systems for periodic measurements of emissions from stationary sources

Contents		Page
European foreword		5
Introduction		7
1	Scope	10
2	Normative references	10
3	Terms and definitions	10
4	Symbols and abbreviations	18
5	General requirements	20
5.1	Application of performance criteria	20
5.2	Ranges to be tested	21
5.2.1	Certification range	21
5.2.2	Supplementary ranges	21
5.2.3	Lower limit of ranges	22
5.2.4	Expression of performance criteria with respect to ranges	22
5.2.5	Ranges of optical in situ P-AMS with variable optical length	22
5.3	Performance testing of P-AMS based on certified AMS previously tested according to EN 15267-3	22
5.4	Equivalence with the SRM	22
5.5	Manufacturing consistency and changes to P-AMS design	22
5.6	Qualifications of testing laboratories	22
6	Common performance criteria for the laboratory test	23
6.1	P-AMS for testing	23
6.2	Evidence of compliance of legal requirements	23
6.3	Output ranges and zero-point	23
6.4	Operational status signals	23
6.5	Degrees of protection provided by enclosures	23
6.6	Response time	23
6.7	Repeatability standard deviation at zero point	23
6.8	Repeatability standard deviation at span point	24
6.9	Lack of fit	24
6.10	Short-term drift at zero point and at span point	24
6.11	Set-up time after transport and influence of ambient temperature	24
6.12	Influence of supply voltage variations	24
6.13	Influence of vibration	24
6.14	Influence of sample gas pressure for in situ P-AMS	24
6.15	Influence of sample gas flow for extractive P-AMS	25
6.16	Cross-sensitivity	25
6.17	Converter efficiency for P-AMS measuring NO _x	25
6.18	Converter efficiency for P-AMS measuring Hg	25
6.19	Response factors for P-AMS measuring TOC	25
6.20	Influences on P-AMS with in-stack sampling chamber	25
6.21	Influences related to storage and transportation	26

7	Common performance criteria for the field test	26
7.1	Response time	26
7.2	Short-term drift at zero point and at span point	26
7.3	Reproducibility	26
8	Specific performance criteria for measured components	26
8.1	General	26
8.2	P-AMS measuring gaseous measured components	26
8.2.1	Performance criteria	26
8.2.2	P-AMS measuring TOC	28
8.2.3	P-AMS measuring Hg	29
8.3	P-AMS measuring particulate matter	29
9	General test requirements	30
10	Test procedures for the laboratory test	32
10.1	P-AMS for testing	32
10.2	Evidence of compliance of legal requirements	32
10.3	Output ranges and zero point	32
10.4	Operational status signals	32
10.5	Degrees of protection provided by enclosures	32
10.6	Response time	33
10.7	Repeatability standard deviation at zero point	34
10.8	Repeatability standard deviation at span point	35
10.9	Lack of fit	35
10.10	Short-term drift at zero point and at span point	37
10.11	Set-up time after transportation and influence of ambient temperature	37
10.12	Influence of supply voltage variations	38
10.13	Influence of vibration	39
10.14	Influence of sample gas pressure for in situ P-AMS	39
10.15	Influence of sample gas flow for extractive P-AMS	40
10.16	Cross-sensitivity	41
10.17	Converter efficiency for P-AMS measuring NOX	42
10.18	Converter efficiency for P-AMS measuring Hg	43
10.19	Response factors for P-AMS measuring TOC	43
10.20	Influences on P-AMS with in-stack sampling chamber	44
10.21	Influences related to storage and transportation	44
11	Requirements for the field test	44
12	Common test procedures for the field test	45
12.1	Response time	45
12.2	Short-term drift at zero point and at span point	45
12.3	Reproducibility	46
13	Equivalence with the SRM	46
14	Measurement uncertainty	47
15	Test report	47
Annex A (informative) European standard reference methods (SRM) and reference methods (RM) ..		49
Annex B (normative) Minimum requirements for a test bench		50
Annex C (normative) Interferents		51
Annex D (informative) Example for the determination of the expanded uncertainty		52
D.1	Determination of uncertainty contributions	52
D.2	Elements required for the uncertainty determinations	52
D.3	Example of an uncertainty calculation for a P-AMS measuring CO	54

D.4	Determination of uncertainty contributions by use of sensitivity coefficients	57
	Annex E (normative) Test of linearity	58
E.1	Description of the test procedure	58
E.2	Establishment of the regression line	58
E.3	Calculation of the residuals of the average concentrations	59
	Annex F (informative) Elements of a performance test report	60
	Bibliography	63