

# ISO 20176:2006-04 (E)

## Road vehicles - H-point machine (HPM II) - Specifications and procedure for H-point determination

---

<b>Contents</b>		<b>Page</b>
Foreword .....		vi
Introduction .....		vii
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Definitions .....</b>	<b>2</b>
3.1	H-point .....	2
3.2	H-point travel path .....	2
3.3	SgRP (Seating Reference Point), R-point, design H-point .....	2
3.4	AHP (Accelerator Heel Point) .....	2
3.5	PRP (Pedal Reference Point) .....	2
3.6	FRP (Floor Reference Point, rear passenger) .....	3
<b>4</b>	<b>Measurement procedure for the three-dimensional H-point machine .....</b>	<b>3</b>
4.1	Summary of installation procedure .....	3
4.1.1	Measured versus design values .....	3
4.2	Prepare vehicle and seat .....	3
4.2.1	Vehicle .....	3
4.2.2	Seat .....	4
4.3	Determine the H-point travel path (optional) .....	4
4.4	Adjust seat to design intent .....	5
4.4.1	Move seat to design intent position .....	5
4.4.2	Torso angle and cushion angle .....	5
4.4.3	Seat in front of test seat .....	6
4.5	Install HPM cushion and back pan assembly .....	7
4.5.1	Install the cushion pan .....	7
4.5.2	Install the back pan .....	7
4.5.3	Level the HPM .....	7
4.6	Load the HPM .....	7
4.6.1	Load the cushion pan .....	8
4.6.2	Load the back pan .....	8
4.7	Soak time .....	8
4.8	Record measurements--digitise HPM points .....	9
4.8.1	H-point .....	9
4.8.2	Torso angle and cushion angle .....	9
4.8.3	Lumbar support prominence .....	9
<b>5</b>	<b>Optional measurements for driver seat .....</b>	<b>9</b>
5.1	Leg and shoe installations .....	9
5.1.1	Mark accelerator pedal centreline .....	9
5.1.2	Install the shoe fixture .....	9
5.1.3	Install the shoe tool .....	9
5.1.4	Install leg segments .....	10
5.2	Record measurements .....	10
5.2.1	Pedal Plane Angle .....	11
5.2.2	Pedal Reference Point .....	11
5.2.3	Accelerator Heel Point .....	11
5.2.4	AHP to PRP lateral offset .....	12

5.2.5	Knee angle and ankle angle .....	12
5.2.6	Thigh angle and hip angle .....	12
6	Optional measurements for 2nd or succeeding row passenger seats .....	12
6.1	Leg and shoe installation .....	12
6.1.1	Install the shoe tool .....	12
6.1.2	Install leg segments .....	13
6.2	Record measurements for rear passengers .....	15
6.2.1	Floor Reference Point (FRP) .....	15
6.2.2	Floor Plane Angle .....	15
6.2.3	Knee clearance and leg room .....	15
7	Additional optional measurements .....	15
7.1	Effective head room .....	15
7.1.1	Install the head room fixture .....	15
7.1.2	Measure effective head room .....	16
8	Remove the HPM .....	16
<b>Annex A (Normative) Description of the Three-Dimensional H-Point Machine (HPM) .....</b>		<b>17</b>
A.1	Availability .....	17
A.2	Major components .....	17
A.2.1	Back pan assembly .....	17
A.2.2	Cushion pan .....	17
A.2.3	Lower leg segment .....	18
A.2.4	Thigh segment .....	18
A.2.5	Shoe tool and shoe fixture .....	19
A.2.6	Spring loaded probe .....	19
A.2.7	Inclinometer (electronic level) .....	20
A.2.8	Weights .....	20
A.2.9	Head room fixture .....	20
A.3	Reference points and angles .....	20
A.3.1	Pivot locations .....	20
A.3.2	Support points .....	20
A.3.3	Divot points .....	21
A.3.4	Key reference points and lines .....	22
A.3.5	Posture angles and LSP .....	23
<b>Annex B (Informative) HPM Specification and Tolerances .....</b>		<b>25</b>
B.1	Tolerances .....	25
B.2	Reference posture for specifications .....	25
B.3	Shoe tool dimensions .....	26
B.4	Lengths .....	26
B.5	Widths .....	26
B.6	Heights .....	27
B.7	Radii .....	27
B.8	Weight, HPM only .....	27
B.9	Support points .....	28
B.10	Divot point locations .....	28
B.11	Muslin cloth .....	29
B.12	Check that HPM is within tolerance specifications .....	29
<b>Annex C (Informative) HPM Field Checking Procedure .....</b>		<b>30</b>
C.1	Purpose .....	30
C.2	Equipment required for checking .....	30
C.2.1	User provided equipment .....	30
C.2.2	Checking fixtures .....	30
C.2.3	Measurement equipment .....	31
C.3	HPM measurement locations .....	32

<b>C.4</b>	<b>Summary of measurements and tolerances .....</b>	<b>33</b>
<b>C.5</b>	<b>Checking procedures .....</b>	<b>34</b>
<b>C.5.1</b>	<b>Cushion pan .....</b>	<b>34</b>
<b>C.5.2</b>	<b>LSP scale checks at -15, +25, and 0 .....</b>	<b>36</b>
<b>C.5.3</b>	<b>Back pan .....</b>	<b>36</b>
<b>C.5.4</b>	<b>Head room probe .....</b>	<b>38</b>
<b>C.5.5</b>	<b>Thigh segment .....</b>	<b>39</b>
<b>C.5.6</b>	<b>Leg .....</b>	<b>39</b>
<b>C.5.7</b>	<b>Data Form .....</b>	<b>41</b>
<b>D.1.1</b>	<b>File format .....</b>	<b>42</b>
<b>D.1.2</b>	<b>Datum lines .....</b>	<b>42</b>
	<b>Bibliography .....</b>	<b>44</b>
	<b>Annex D (Informative) H-Point Design (HPD) tool description .....</b>	<b>42</b>
<b>D.1</b>	<b>H-Point Design tool (HPD) .....</b>	<b>42</b>