

# DIN EN ISO 2811-1:2011-06 (E)

## Paints and varnishes - Determination of density - Part 1: Pyknometer method (ISO 2811-1:2011)

---

<b>Contents</b>		Page
<b>Foreword</b> .....		<b>3</b>
<b>1</b>	<b>Scope</b> .....	<b>4</b>
<b>2</b>	<b>Normative references</b> .....	<b>4</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>4</b>
<b>4</b>	<b>Principle</b> .....	<b>4</b>
<b>5</b>	<b>Temperature</b> .....	<b>5</b>
<b>6</b>	<b>Apparatus</b> .....	<b>5</b>
<b>7</b>	<b>Sampling</b> .....	<b>5</b>
<b>8</b>	<b>Procedure</b> .....	<b>5</b>
<b>8.1</b>	<b>General</b> .....	<b>5</b>
<b>8.2</b>	<b>Determination</b> .....	<b>6</b>
<b>9</b>	<b>Calculation</b> .....	<b>7</b>
<b>10</b>	<b>Precision</b> .....	<b>7</b>
<b>10.1</b>	<b>Repeatability limit, <math>r</math></b> .....	<b>7</b>
<b>10.2</b>	<b>Reproducibility limit, <math>R</math></b> .....	<b>7</b>
<b>11</b>	<b>Test report</b> .....	<b>8</b>
<b>Annex A (informative) Example of a calibration method</b> .....		<b>9</b>
<b>Annex B (informative) Temperature variation</b> .....		<b>11</b>
<b>Bibliography</b> .....		<b>13</b>