

ISO 2811-1:2011-03 (E)

Paints and varnishes - Determination of density - Part 1: Pyknometer method

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	1
5	Temperature	2
6	Apparatus	2
7	Sampling	2
8	Procedure	2
8.1	General	2
8.2	Determination	3
9	Calculation	4
10	Precision	4
10.1	Repeatability limit, r	4
10.2	Reproducibility limit, R	4
11	Test report	5
Annex A (informative) Example of a calibration method		6
Annex B (informative) Temperature variation		8
Bibliography		10