

DIN EN ISO 16474-2:2014-03 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 2: Xenon-arc lamps (ISO 16474-2:2013)

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Principle	6
5	Apparatus	7
5.1	Laboratory light source	7
5.2	Test chamber	8
5.3	Radiometer	9
5.4	Black-standard/black-panel thermometer	9
5.5	Wetting and humidity-control equipment	9
5.6	Specimen holders	9
5.7	Apparatus to assess changes in properties	10
6	Test specimens	10
7	Exposure conditions	10
7.1	Radiation	10
7.2	Temperature	10
7.3	Relative humidity of chamber air	11
7.4	Spray cycle	12
7.5	Cycles with dark periods	12
7.6	Sets of exposure conditions	13
8	Procedure	13
8.1	General	13
8.2	Mounting the test specimens	13
8.3	Exposure	13
8.4	Duration of test	14
8.5	Measurement of radiant exposure	14
8.6	Determination of changes in properties after exposure	14
9	Test report	14
Annex A (informative) Filtered xenon-arc radiation -- Spectral power distribution		15
Annex B (normative) Additional exposure cycles		17
Bibliography		19