

ISO 16474-1:2013-11 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 1: General guidance

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
4.1	General	2
4.2	Significance	2
4.3	Use of accelerated tests with laboratory light sources	4
5	Requirements for laboratory exposure devices	4
5.1	Irradiance	4
5.2	Temperature	6
5.3	Humidity and wetting	8
5.4	Other requirements for the exposure device	9
6	Test specimens -- Preparation, replicates, storage and conditioning	9
6.1	Handling of test specimens	9
6.2	Form, shape, preparation	9
6.3	Number of test specimens	10
6.4	Storage and conditioning	10
7	Test conditions and procedure	11
7.1	Set points for exposure conditions	11
7.2	Property measurements on test specimens	11
8	Periods of exposure and evaluation of test results	12
8.1	General	12
8.2	Sampling	12
8.3	Determination of changes in properties after exposure	12
8.4	Use of control materials	12
8.5	Use of results in specifications	12
9	Test report	13
Annex A (informative)	Procedure for measuring the irradiance uniformity in the specimen exposure area	15
Annex B (informative)	Factors that decrease the degree of correlation between artificial accelerated weathering or artificial accelerated irradiation exposures and actual- use exposures	18
Annex C (informative)	Solar spectral irradiance standard	21
Bibliography		22