

ISO 8502-6:2020-04 (E)

Preparation of steel substrates before application of paints and related products - Tests for the assessment of surface cleanliness - Part 6: Extraction of water soluble contaminants for analysis (Bresle method)

Contents		Page
Foreword	iv
Introduction	v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Apparatus and materials	2
6	Procedure	3
	6.1 Selection of test surface.....	3
	6.2 Blank test.....	3
	6.3 Extraction by patch or sleeve by injection.....	3
	6.4 Extraction by sleeve by pre-filling.....	5
7	Analyses	5
8	Test report	5
Annex A (normative) Leak test for type testing of adhesive cells (patches and sleeves)		9
Bibliography		11