

# ISO 8502-6:2020-04 (E)

## Preparation of steel substrates before application of paints and related products - Tests for the assessment of surface cleanliness - Part 6: Extraction of water soluble contaminants for analysis (Bresle method)

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>Introduction</b> .....		<b>v</b>
<b>1 Scope</b> .....		<b>1</b>
<b>2 Normative references</b> .....		<b>1</b>
<b>3 Terms and definitions</b> .....		<b>1</b>
<b>4 Principle</b> .....		<b>2</b>
<b>5 Apparatus and materials</b> .....		<b>2</b>
<b>6 Procedure</b> .....		<b>3</b>
6.1 Selection of test surface.....		3
6.2 Blank test.....		3
6.3 Extraction by patch or sleeve by injection.....		3
6.4 Extraction by sleeve by pre-filling.....		5
<b>7 Analyses</b> .....		<b>5</b>
<b>8 Test report</b> .....		<b>5</b>
<b>Annex A (normative) Leak test for type testing of adhesive cells (patches and sleeves)</b> .....		<b>9</b>
<b>Bibliography</b> .....		<b>11</b>