

# DIN EN ISO 19403-2:2024-11 (E)

## Paints and varnishes - Wettability - Part 2: Determination of the surface free energy of solid surfaces by measuring the contact angle (ISO 19403-2:2024)

---

<b>Contents</b>		<b>Page</b>
<b>European foreword</b>	.....	<b>3</b>
<b>Foreword</b>	.....	<b>4</b>
<b>1 Scope</b>	.....	<b>5</b>
<b>2 Normative references</b>	.....	<b>5</b>
<b>3 Terms and definitions</b>	.....	<b>5</b>
<b>4 Principle</b>	.....	<b>5</b>
<b>5 Apparatus and materials</b>	.....	<b>6</b>
<b>6 Sampling</b>	.....	<b>7</b>
<b>7 Procedure</b>	.....	<b>7</b>
7.1 General for measuring on the horizontal drop	.....	7
7.1.1 Setting up the contact angle measuring system	.....	7
7.1.2 Test conditions	.....	8
7.1.3 Conditioning of the test panels	.....	8
7.2 Measurement	.....	8
7.2.1 General	.....	8
7.2.2 Static method	.....	8
7.2.3 Dynamic method (progressive contact angle)	.....	9
7.2.4 Determination of the contact angle	.....	10
<b>8 Evaluation</b>	.....	<b>10</b>
8.1 General	.....	10
8.2 Owens-Wendt-Rabel-Kaelble method (OWRK method)	.....	10
8.3 Wu method	.....	11
<b>9 Precision</b>	.....	<b>12</b>
9.1 General	.....	12
9.2 Repeatability limit, <i>r</i>	.....	12
9.3 Reproducibility limit, <i>R</i>	.....	12
9.4 Calculation in accordance with the Owens-Wendt-Rabel-Kaelble method	.....	12
<b>10 Test report</b>	.....	<b>13</b>
<b>Annex A (informative) Notes on measuring practice</b>	.....	<b>14</b>
<b>Bibliography</b>	.....	<b>18</b>