

# ISO 4628-1:2003-09 (E)

## Paints and varnishes - Evaluation of degradation of coatings; Designation of quantity and size of defects, and of intensity of uniform changes in appearance - Part 1: General introduction and designation system

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	General principles of the designation system .....	1
3	Assessment of defects and of intensity of changes .....	1
3.1	General .....	1
3.2	Designation of quantity of defects .....	2
3.3	Designation of size of defects .....	2
3.4	Designation of intensity of changes .....	2
4	Expression of results .....	3
5	Test report .....	3