

DIN EN ISO 8502-6:2006-10 (E)

Preparation of steel substrates before application of paints and related products -
Tests for the assessment of surface cleanliness - Part 6: Extraction of soluble
contaminants for analysis - The Bresle method (ISO 8502-6:2006)

Contents		Page
Foreword		2
Introduction		4
1 Scope		5
2 Normative references		5
3 Principle		5
4 Apparatus and materials		6
5 Procedure		6
6 Test report		7
Annex A (normative) Leak test for type testing of patches		10