

# DIN EN ISO 8502-6:2006-10 (E)

Preparation of steel substrates before application of paints and related products -  
Tests for the assessment of surface cleanliness - Part 6: Extraction of soluble  
contaminants for analysis - The Bresle method (ISO 8502-6:2006)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		2
Introduction .....		4
1 <b>Scope</b> .....		5
2 <b>Normative references</b> .....		5
3 <b>Principle</b> .....		5
4 <b>Apparatus and materials</b> .....		6
5 <b>Procedure</b> .....		6
6 <b>Test report</b> .....		7
<b>Annex A (normative) Leak test for type testing of patches</b> .....		<b>10</b>