

ISO 2808:2007-02 (E)

Paints and varnishes - Determination of film thickness

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Determination of wet-film thickness	3
4.1	General	3
4.2	Mechanical methods	3
4.2.1	Principle	3
4.2.2	Field of application	3
4.2.3	General	3
4.2.4	Method 1A -- Comb gauge	4
4.2.5	Method 1B -- Wheel gauge	5
4.2.6	Method 1C -- Dial gauge	6
4.3	Gravimetric method	7
4.3.1	Principle	7
4.3.2	Field of application	7
4.3.3	General	7
4.3.4	Method 2 -- By difference in mass	7
4.4	Photothermal method	8
4.4.1	Principle	8
4.4.2	Field of application	8
4.4.3	General	9
4.4.4	Method 3 -- Determination using thermal properties	9
5	Determination of dry-film thickness	9
5.1	General	9
5.2	Mechanical methods	9
5.2.1	Principle	9
5.2.2	Field of application	10
5.2.3	General	10
5.2.4	Method 4A -- By difference in thickness	11
5.2.5	Method 4B -- Depth gauging	13
5.2.6	Method 4C -- Surface profile scanning	15
5.3	Gravimetric method	16
5.3.1	Principle	16
5.3.2	Field of application	16
5.3.3	General	16
5.3.4	Method 5 -- By difference in mass	16
5.4	Optical methods	17
5.4.1	Principle	17
5.4.2	Field of application	18
5.4.3	General	18
5.4.4	Method 6A -- Cross-sectioning	19
5.4.5	Method 6B -- Wedge cut	20
5.5	Magnetic methods	20
5.5.1	General	20

5.5.2	Principle	20
5.5.3	Field of application	20
5.5.4	General	21
5.5.5	Method 7A -- Magnetic pull-off gauge	21
5.5.6	Method 7B -- Magnetic-flux gauge	22
5.5.7	Method 7C -- Magnetic-induction gauge	22
5.5.8	Method 7D -- Eddy-current gauge	23
5.6	Radiological method	24
5.6.1	Principle	24
5.6.2	Field of application	24
5.6.3	General	24
5.6.4	Method 8 -- Beta backscatter method	25
5.7	Photothermal method	25
5.7.1	Principle	25
5.7.2	Field of application	26
5.7.3	General	26
5.7.4	Method 9 -- Determination using thermal properties	27
5.8	Acoustic method	27
5.8.1	Principle	27
5.8.2	Field of application	27
5.8.3	General	27
5.8.4	Method 10 -- Ultrasonic thickness gauge	28
6	Determination of thickness of uncured powder layers	28
6.1	General	28
6.2	Gravimetric method	29
6.2.1	Principle	29
6.2.2	Field of application	29
6.2.3	General	29
6.2.4	Method 11 -- By difference in mass	29
6.3	Magnetic methods	29
6.3.1	Principle	29
6.3.2	Field of application	29
6.3.3	General	30
6.3.4	Method 12A -- Magnetic-induction gauge	30
6.3.5	Method 12B -- Eddy-current gauge	31
6.4	Photothermal method	31
6.4.1	Principle	31
6.4.2	Field of application	31
6.4.3	General	31
6.4.4	Method 13 -- Determination using thermal properties	31
7	Measurement of film thickness on rough surfaces	32
7.1	General	32
7.2	Apparatus and materials	33
7.3	Procedure	33
7.3.1	Verification	33
7.3.2	Measurement	33
7.3.3	Number of readings	33
8	Test report	33
	Annex A (informative) Overview of methods	35
	Bibliography	38