

# ISO 13319:2007-07 (E)

## Determination of particle size distributions - Electrical sensing zone method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Symbols .....</b>	<b>2</b>
<b>5</b>	<b>Principle .....</b>	<b>3</b>
<b>6</b>	<b>General operation .....</b>	<b>4</b>
<b>6.1</b>	<b>Response .....</b>	<b>4</b>
<b>6.2</b>	<b>Size limits .....</b>	<b>4</b>
<b>6.3</b>	<b>Effect of coincident particle passage .....</b>	<b>4</b>
<b>6.4</b>	<b>Dead time .....</b>	<b>5</b>
<b>7</b>	<b>Repeatability of counts .....</b>	<b>6</b>
<b>8</b>	<b>Operational procedures .....</b>	<b>6</b>
<b>8.1</b>	<b>Instrument location .....</b>	<b>6</b>
<b>8.2</b>	<b>Linearity of the aperture/amplifier system .....</b>	<b>6</b>
<b>8.3</b>	<b>Linearity of the counting system .....</b>	<b>7</b>
<b>8.4</b>	<b>Choice of electrolyte solution .....</b>	<b>7</b>
<b>8.5</b>	<b>Preparation of electrolyte solution .....</b>	<b>7</b>
<b>8.6</b>	<b>Recommended sampling, sample splitting, sample preparation and dispersion .....</b>	<b>8</b>
<b>8.7</b>	<b>Choice of aperture(s) and analysis volume(s) .....</b>	<b>9</b>
<b>8.8</b>	<b>Clearing an aperture blockage .....</b>	<b>10</b>
<b>8.9</b>	<b>Stability of dispersion .....</b>	<b>10</b>
<b>8.10</b>	<b>Calibration .....</b>	<b>11</b>
<b>9</b>	<b>Analysis .....</b>	<b>11</b>
<b>10</b>	<b>Calculation of results .....</b>	<b>12</b>
<b>11</b>	<b>Instrument qualification .....</b>	<b>12</b>
<b>11.1</b>	<b>General .....</b>	<b>12</b>
<b>11.2</b>	<b>Report .....</b>	<b>12</b>
<b>Annex A (informative) Calibration for the measurement of porous and conductive particles .....</b>		<b>13</b>
<b>Annex B (informative) Technique using two (or more) apertures .....</b>		<b>16</b>
<b>Annex C (informative) Chi-squared test of the correctness of instrument operation or sample preparation .....</b>		<b>18</b>
<b>Annex D (informative) Table of materials and electrolyte solutions .....</b>		<b>20</b>
<b>Annex E (informative) Mass integration method .....</b>		<b>30</b>
<b>Annex F (informative) Calibration and control of frequently used apertures .....</b>		<b>36</b>
<b>Bibliography .....</b>		<b>37</b>