

ISO/TS 5660-3:2012-12 (E)

Reaction-to-fire tests - Heat release, smoke production and mass loss rate - Part 3: Guidance on measurement

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Capability and limitations of the cone calorimeter	1
4	Calibration of the cone calorimeter	2
4.1	General	2
4.2	Heat flux meter calibration (see 6.12 and 10.3.1 of ISO 5660-1:2002)	2
4.3	Calibration frequency	2
4.4	Oxygen analyser calibration (see 10.1.5, 10.1.6 and 10.2.3 of ISO 5660-1:2002)	3
4.5	Determining orifice plate calibration factor	4
4.6	Additional comments on the orifice calibration factor	4
4.7	Calibration of smoke measurement system	5
4.8	Precautions in relation to water/CO ₂ removal	6
4.9	Routine maintenance	6
5	Test specimen preparation and presentation	6
5.1	General	6
5.2	Specimen trays and edge retainer frame	8
6	Selection of heat flux	9
7	Ignition protocols	11
8	Guidance on the testing of non-standard products	11
8.1	General	11
8.2	Non-planar products	11
8.3	Radiation transfer considerations	13
8.4	Thermally mobile specimens	19
9	Composites and layered products	20
9.1	General	20
9.2	Non-homogeneous products	20
9.3	Specimens with short test duration	20
10	Liquids	21
10.1	General	21
10.2	Testing without the radiant heater	21
10.3	Testing with the radiant heater	22
11	The theory of oxygen consumption calorimetry	22
11.1	General	22
11.2	Silicones	23
11.3	Effect of additives and fillers	24
12	Start and end of test	25

12.1	Start of test	25
12.2	End of test	25
13	Recommendations for presentation of data	25
13.1	Current situation	25
13.2	Additional useful data	26
13.3	Recommendations	29
Annex A (informative) Predictive methods from ISO 5660-1 data		30
Annex B (informative) Effect of additives and fillers		37
Annex C (informative) Measurements at low levels of heat release		40
Bibliography		42