

# DIN ISO 9022-22:2012-10 (E)

## Optics and photonics - Environmental test methods - Part 22: Combined cold, dry heat or temperature change with bump or random vibration (ISO 9022-22:2012)

---

<b>Contents</b>		<b>Page</b>
National foreword .....		3
National Annex NA (informative) Bibliography .....		4
Introduction .....		5
1	Scope .....	6
2	Normative references .....	6
3	Terms and definitions .....	6
4	General information and test conditions .....	6
5	Conditioning .....	7
5.1	General .....	7
5.2	Conditioning method 22: Cold, dry heat or temperature change combined with bump or random vibration .....	7
6	Procedure .....	8
6.1	General .....	8
6.2	Test sequence with cold or dry heat testing .....	8
6.3	Test sequence with temperature change .....	8
6.4	Operating condition of specimen .....	8
6.5	Mechanical conditioning of specimen .....	9
7	Environmental test code .....	9
8	Specification .....	10
Annex A (informative) Explanatory notes .....		11
Bibliography .....		12