

DIN ISO 9022-22:2012-10 (E)

Optics and photonics - Environmental test methods - Part 22: Combined cold, dry heat or temperature change with bump or random vibration (ISO 9022-22:2012)

Contents		Page
National foreword		3
National Annex NA (informative) Bibliography		4
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	General information and test conditions	6
5	Conditioning	7
5.1	General	7
5.2	Conditioning method 22: Cold, dry heat or temperature change combined with bump or random vibration	7
6	Procedure	8
6.1	General	8
6.2	Test sequence with cold or dry heat testing	8
6.3	Test sequence with temperature change	8
6.4	Operating condition of specimen	8
6.5	Mechanical conditioning of specimen	9
7	Environmental test code	9
8	Specification	10
Annex A (informative) Explanatory notes		11
Bibliography		12