

ISO 9022-2:2015-03 (E)

Optics and photonics - Environmental test methods - Part 2: Cold, heat and humidity

Contents	Page
Foreword	iv
Introduction	vi
1 Scope	1
2 Normative references	1
3 General information and test conditions	1
4 Conditioning	1
4.1 General	1
4.2 Constant stress conditions	2
4.2.1 General	2
4.2.2 Conditioning method 10: Cold	2
4.2.3 Conditioning method 11: Dry heat	2
4.2.4 Conditioning method 12: Damp heat	2
4.2.5 Conditioning method 13: Condensation	2
4.3 Cycling exposure conditions	3
4.3.1 General	3
4.3.2 Conditioning method 14: Slow temperature change	3
4.3.3 Conditioning method 15: Rapid temperature change (temperature shock)	4
4.3.4 Conditioning method 16: Damp heat, cyclic	5
5 Procedure	7
5.1 General	7
5.2 Pre-test	7
6 Environmental test code	7
7 Specification	8