

ISO 9022-2:2015-03 (E)

Optics and photonics - Environmental test methods - Part 2: Cold, heat and humidity

| Contents | Page |
|--|-------------|
| Foreword | iv |
| Introduction | vi |
| 1 Scope | 1 |
| 2 Normative references | 1 |
| 3 General information and test conditions | 1 |
| 4 Conditioning | 1 |
| 4.1 General | 1 |
| 4.2 Constant stress conditions | 2 |
| 4.2.1 General | 2 |
| 4.2.2 Conditioning method 10: Cold | 2 |
| 4.2.3 Conditioning method 11: Dry heat | 2 |
| 4.2.4 Conditioning method 12: Damp heat | 2 |
| 4.2.5 Conditioning method 13: Condensation | 2 |
| 4.3 Cycling exposure conditions | 3 |
| 4.3.1 General | 3 |
| 4.3.2 Conditioning method 14: Slow temperature change | 3 |
| 4.3.3 Conditioning method 15: Rapid temperature change (temperature shock) | 4 |
| 4.3.4 Conditioning method 16: Damp heat, cyclic | 5 |
| 5 Procedure | 7 |
| 5.1 General | 7 |
| 5.2 Pre-test | 7 |
| 6 Environmental test code | 7 |
| 7 Specification | 8 |