

# ISO 9022-3:2015-03 (E)

## Optics and photonics - Environmental test methods - Part 3: Mechanical stress

---

<b>Contents</b>		<b>Page</b>
Foreword	.....	iv
Introduction	.....	vi
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>General information and test conditions</b> .....	<b>1</b>
<b>4</b>	<b>Conditioning</b> .....	<b>2</b>
4.1	Conditioning method 30: Shock.....	2
4.2	Conditioning method 31: Bump.....	2
4.3	Conditioning method 32: Drop and topple.....	3
4.4	Conditioning method 33: Free fall.....	3
4.5	Conditioning method 34: Bounce.....	3
4.6	Conditioning method 35: Steady-state acceleration, centrifugal.....	4
4.7	Conditioning method 36: Sinusoidal vibration.....	4
	4.7.1 General.....	4
	4.7.2 Vibration testing using sweep frequencies.....	4
	4.7.3 Vibration fatigue test using characteristic frequencies.....	5
4.8	Conditioning method 37: Random vibration (wide-band) digitally controlled.....	5
<b>5</b>	<b>Procedure</b> .....	<b>6</b>
<b>6</b>	<b>Environmental test code</b> .....	<b>6</b>
<b>7</b>	<b>Specification</b> .....	<b>6</b>