

# ISO 9022-8:2015-03 (E)

## Optics and photonics - Environmental test methods - Part 8: High internal pressure, low internal pressure, immersion

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>Introduction</b> .....		<b>vi</b>
<b>1 Scope</b> .....		<b>1</b>
<b>2 Normative references</b> .....		<b>1</b>
<b>3 General information and test conditions</b> .....		<b>1</b>
<b>4 Conditioning</b> .....		<b>1</b>
4.1 Conditioning method 80: High internal pressure.....		1
4.2 Conditioning method 81: Low internal pressure.....		1
4.3 Conditioning method 82: Immersion.....		2
<b>5 Procedure</b> .....		<b>2</b>
5.1 General.....		2
5.2 Conditioning method 82: Preconditioning of specimen and initial test.....		2
5.3 Conditioning methods 80 and 81: Pressure change curve.....		2
5.4 State of operation 2.....		3
5.5 Conditioning method 82: Recovery and final test.....		3
5.6 Conditioning method 82: Evaluation.....		3
<b>6 Environmental test code</b> .....		<b>3</b>
<b>7 Specification</b> .....		<b>3</b>
<b>Annex A (informative) Explanatory notes</b> .....		<b>5</b>