

ISO 9022-8:2015-03 (E)

Optics and photonics - Environmental test methods - Part 8: High internal pressure, low internal pressure, immersion

| Contents | | Page |
|---|--|-------------|
| Foreword | | iv |
| Introduction | | vi |
| 1 Scope | | 1 |
| 2 Normative references | | 1 |
| 3 General information and test conditions | | 1 |
| 4 Conditioning | | 1 |
| 4.1 Conditioning method 80: High internal pressure..... | | 1 |
| 4.2 Conditioning method 81: Low internal pressure..... | | 1 |
| 4.3 Conditioning method 82: Immersion..... | | 2 |
| 5 Procedure | | 2 |
| 5.1 General..... | | 2 |
| 5.2 Conditioning method 82: Preconditioning of specimen and initial test..... | | 2 |
| 5.3 Conditioning methods 80 and 81: Pressure change curve..... | | 2 |
| 5.4 State of operation 2..... | | 3 |
| 5.5 Conditioning method 82: Recovery and final test..... | | 3 |
| 5.6 Conditioning method 82: Evaluation..... | | 3 |
| 6 Environmental test code | | 3 |
| 7 Specification | | 3 |
| Annex A (informative) Explanatory notes | | 5 |