

# DIN ISO 9022-12:2016-02 (E)

## Optics and photonics - Environmental test methods - Part 12: Contamination (ISO 9022-12:2015)

---

<b>Contents</b>	<b>Page</b>
<b>National Foreword</b> .....	<b>3</b>
<b>National Annex NA (informative) Bibliography</b> .....	<b>4</b>
<b>Introduction</b> .....	<b>5</b>
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 General information and test conditions</b> .....	<b>6</b>
3.1 Specimen.....	6
3.2 Test pad.....	7
3.3 Test weight and arrangement of test pads.....	8
<b>4 Conditioning</b> .....	<b>9</b>
4.1 General.....	9
4.2 Conditioning method 86: Basic cosmetic substances and artificial hand sweat.....	9
4.3 Conditioning method 87: Laboratory agents.....	9
4.4 Conditioning method 88: Production plant resources.....	9
4.5 Conditioning method 89: Fuels and resources for aircraft, naval vessels, and land vehicles.....	9
<b>5 Procedure</b> .....	<b>12</b>
5.1 General.....	12
5.2 Preconditioning.....	12
5.3 Test sequence.....	13
5.4 Recovery.....	13
5.5 Evaluation.....	13
5.6 General level for acceptance.....	13
<b>6 Environmental test code</b> .....	<b>14</b>
<b>7 Specification</b> .....	<b>14</b>
<b>Annex A (normative) Determination of pH value of aqueous extract of pad materials</b> .....	<b>15</b>