

DIN ISO 9022-12:2016-02 (E)

Optics and photonics - Environmental test methods - Part 12: Contamination (ISO 9022-12:2015)

Contents	Page
National Foreword	3
National Annex NA (informative) Bibliography	4
Introduction	5
1 Scope	6
2 Normative references	6
3 General information and test conditions	6
3.1 Specimen.....	6
3.2 Test pad.....	7
3.3 Test weight and arrangement of test pads.....	8
4 Conditioning	9
4.1 General.....	9
4.2 Conditioning method 86: Basic cosmetic substances and artificial hand sweat.....	9
4.3 Conditioning method 87: Laboratory agents.....	9
4.4 Conditioning method 88: Production plant resources.....	9
4.5 Conditioning method 89: Fuels and resources for aircraft, naval vessels, and land vehicles.....	9
5 Procedure	12
5.1 General.....	12
5.2 Preconditioning.....	12
5.3 Test sequence.....	13
5.4 Recovery.....	13
5.5 Evaluation.....	13
5.6 General level for acceptance.....	13
6 Environmental test code	14
7 Specification	14
Annex A (normative) Determination of pH value of aqueous extract of pad materials	15