

ISO 14242-2:2016-09 (E)

Implants for surgery - Wear of total hip-joint prostheses - Part 2: Methods of measurement

Contents	Page
Foreword	iv
1 Scope	1
2 Normative reference	1
3 Terms and definitions	1
4 Gravimetric method	1
4.1 Principle	1
4.2 Reagents and materials	1
4.3 Apparatus	2
4.4 Preparation of test specimen for gravimetric measurements	2
4.5 Procedure for gravimetric measurement	3
5 Dimensional change method	3
5.1 Principle	3
5.2 Apparatus	3
5.3 Procedure for dimensional change measurement	4
6 Test report	4