

ISO 14242-2:2016-09 (E)

Implants for surgery - Wear of total hip-joint prostheses - Part 2: Methods of measurement

Contents		Page
Foreword		iv
1	Scope	1
2	Normative reference	1
3	Terms and definitions	1
4	Gravimetric method	1
4.1	Principle	1
4.2	Reagents and materials	1
4.3	Apparatus	2
4.4	Preparation of test specimen for gravimetric measurements	2
4.5	Procedure for gravimetric measurement	3
5	Dimensional change method	3
5.1	Principle	3
5.2	Apparatus	3
5.3	Procedure for dimensional change measurement	4
6	Test report	4