

ISO 10110-7:2017-08 (E)

Optics and photonics - Preparation of drawings for optical elements and systems - Part 7: Surface imperfections

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Indication in drawings	3
4.1	General	3
4.2	Dimensional specification method for optical elements and assemblies	3
4.2.1	Maximum permissible surface imperfections	3
4.2.2	Surface imperfection indication for the dimensional specification method	6
4.2.3	Imperfections with a smaller grade number in the dimensional specification method	6
4.2.4	Concentrations of surface imperfections in the dimensional specification method	6
4.2.5	Test methods for the dimensional specification method	7
4.3	Visibility specification method for optical elements and assemblies	7
4.3.1	Maximum permissible surface imperfections	7
4.3.2	Visibility specification imperfections with smaller grade number	10
4.3.3	Concentrations of visibility imperfections	10
4.3.4	Test method for visibility	10
4.4	Location of the indication	10
Bibliography		12