

# ISO 10110-18:2018-12 (E)

## Optics and photonics - Preparation of drawings for optical elements and systems - Part 18: Stress bi refraction, bubbles and inclusions, homogeneity, and striae

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.1</b>	<b>Terms for stress birefringence .....</b>	<b>1</b>
<b>3.2</b>	<b>Terms for bubbles and inclusions .....</b>	<b>2</b>
<b>3.3</b>	<b>Terms for homogeneity and striae .....</b>	<b>2</b>
<b>4</b>	<b>Specification of raw material and finished assemblies .....</b>	<b>2</b>
<b>4.1</b>	<b>Raw material .....</b>	<b>2</b>
<b>4.2</b>	<b>Finished assemblies .....</b>	<b>2</b>
<b>5</b>	<b>Stress birefringence .....</b>	<b>3</b>
<b>5.1</b>	<b>Principle of specification .....</b>	<b>3</b>
<b>5.2</b>	<b>Indication in drawings .....</b>	<b>3</b>
<b>5.2.1</b>	<b>Indication codes .....</b>	<b>3</b>
<b>5.2.2</b>	<b>Structure of the indication .....</b>	<b>3</b>
<b>5.3</b>	<b>Examples of indications for stress birefringence .....</b>	<b>3</b>
<b>6</b>	<b>Bubbles and inclusions .....</b>	<b>3</b>
<b>6.1</b>	<b>General .....</b>	<b>3</b>
<b>6.2</b>	<b>Principle of specification .....</b>	<b>3</b>
<b>6.3</b>	<b>Indication in drawings .....</b>	<b>4</b>
<b>6.3.1</b>	<b>Indication codes .....</b>	<b>4</b>
<b>6.3.2</b>	<b>Structure of the indication .....</b>	<b>4</b>
<b>6.4</b>	<b>Accumulation rule .....</b>	<b>4</b>
<b>6.5</b>	<b>Concentration rule .....</b>	<b>5</b>
<b>6.6</b>	<b>Examples of indications for bubbles .....</b>	<b>5</b>
<b>7</b>	<b>Homogeneity and striae .....</b>	<b>5</b>
<b>7.1</b>	<b>General .....</b>	<b>5</b>
<b>7.2</b>	<b>Indication in drawings .....</b>	<b>5</b>
<b>7.2.1</b>	<b>Indication codes .....</b>	<b>5</b>
<b>7.2.2</b>	<b>Structure of the indication .....</b>	<b>6</b>
<b>7.3</b>	<b>Homogeneity .....</b>	<b>6</b>
<b>7.3.1</b>	<b>Principle of specification .....</b>	<b>6</b>
<b>7.3.2</b>	<b>Quality classes .....</b>	<b>6</b>
<b>7.3.3</b>	<b>Focus term .....</b>	<b>7</b>
<b>7.4</b>	<b>Striae .....</b>	<b>7</b>
<b>7.4.1</b>	<b>Principles of specification .....</b>	<b>7</b>
<b>7.4.2</b>	<b>Density classes for striae .....</b>	<b>7</b>
<b>7.4.3</b>	<b>Wavefront deviation classes for striae .....</b>	<b>7</b>
<b>7.4.4</b>	<b>Comparison of density and wavefront quality classes for striae .....</b>	<b>8</b>
<b>7.4.5</b>	<b>Multiple orthogonal directions .....</b>	<b>8</b>
<b>7.5</b>	<b>Examples of indications for homogeneity and striae .....</b>	<b>8</b>

8	Indications for "no requirement" or "default" .....	9
9	Indications on drawings .....	9
9.1	Table field .....	9
9.2	Drawing field .....	9
10	Indications for other optical material tolerances .....	9
11	Examples of indications on drawings .....	9
11.1	Example 1: Raw material properties in the drawing region .....	9
11.2	Example 2: Finished part bubble specification .....	10
11.3	Example 3: Finished part, all three properties .....	10
11.4	Example 4: System example .....	11
11.5	Example 5: Tabulation example .....	11
	Annex A (informative) Stress optical constant and stress birefringence .....	12
	Annex B (informative) Guidance for stress birefringence in optical glass .....	13
	Annex C (informative) Guidance for bubble grades in optical glass .....	15
	Annex D (informative) Guidance for homogeneity in optical glass .....	18
	Annex E (informative) Guidance for striae in optical glass .....	20
	Bibliography .....	22