

DIN ISO 10110-18:2019-09 (E)

Optics and photo nics - Preparation of drawings for optical elements and systems - Part 18: Stress birefringence, bubbles and inclusions, homogeneity, and striae (ISO 10110-18:2 018)

Contents		Page
8	Indications for "no requirement" or "default"	16
9	Indications on drawings	16
9.1	Table field	16
9.2	Drawing field	16
10	Indications for other optical material tolerances	16
11	Examples of indications on drawings	16
11.1	Example 1: Raw material properties in the drawing region	16
11.2	Example 2: Finished part bubble specification	17
11.3	Example 3: Finished part, all three properties	17
11.4	Example 4: System example	18
11.5	Example 5: Tabulation example	18
Annex A (informative) Stress optical constant and stress birefringence		19
Annex B (informative) Guidance for stress birefringence in optical glass		20
Annex C (informative) Guidance for bubble grades in optical glass		22
Annex D (informative) Guidance for homogeneity in optical glass		25
Annex E (informative) Guidance for striae in optical glass		27
Bibliography		29