

# DIN ISO 10110-18:2019-09 (E)

## Optics and photo nics - Preparation of drawings for optical elements and systems - Part 18: Stress birefringence, bubbles and inclusions, homogeneity, and striae (ISO 10110-18:2 018)

---

<b>Contents</b>		<b>Page</b>
<b>8</b>	<b>Indications for "no requirement" or "default" .....</b>	<b>16</b>
<b>9</b>	<b>Indications on drawings .....</b>	<b>16</b>
<b>9.1</b>	<b>Table field .....</b>	<b>16</b>
<b>9.2</b>	<b>Drawing field .....</b>	<b>16</b>
<b>10</b>	<b>Indications for other optical material tolerances .....</b>	<b>16</b>
<b>11</b>	<b>Examples of indications on drawings .....</b>	<b>16</b>
<b>11.1</b>	<b>Example 1: Raw material properties in the drawing region .....</b>	<b>16</b>
<b>11.2</b>	<b>Example 2: Finished part bubble specification .....</b>	<b>17</b>
<b>11.3</b>	<b>Example 3: Finished part, all three properties .....</b>	<b>17</b>
<b>11.4</b>	<b>Example 4: System example .....</b>	<b>18</b>
<b>11.5</b>	<b>Example 5: Tabulation example .....</b>	<b>18</b>
<b>Annex A (informative) Stress optical constant and stress birefringence .....</b>		<b>19</b>
<b>Annex B (informative) Guidance for stress birefringence in optical glass .....</b>		<b>20</b>
<b>Annex C (informative) Guidance for bubble grades in optical glass .....</b>		<b>22</b>
<b>Annex D (informative) Guidance for homogeneity in optical glass .....</b>		<b>25</b>
<b>Annex E (informative) Guidance for striae in optical glass .....</b>		<b>27</b>
<b>Bibliography .....</b>		<b>29</b>