

ISO 23701:2023-04 (E)

Optics and photonics - Laser and laser-related equipment - Photothermal technique for absorption measurement and mapping of optical laser components

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols used and units of measure	2
5 Test method	2
5.1 Test principle	2
5.1.1 General	2
5.1.2 Photothermal lensing (TL)	3
5.1.3 Photothermal deflection (PTD)	3
5.1.4 Rules for selecting reflected and transmitted photothermal detection schemes	3
5.2 Measurement arrangement and test equipment	3
5.2.1 Photothermal detection arrangement	3
5.2.2 Pump laser	6
5.2.3 Probe laser	6
5.2.4 Translation stage	6
5.2.5 Detection unit	7
5.2.6 Data acquisition and processing	7
5.2.7 Environment	7
5.3 Preparation of test sample	7
6 Test procedure	7
6.1 General	7
6.2 Measurements of photothermal amplitude and phase	8
6.3 Maps of photothermal amplitude and phase	8
6.4 Calibration of photothermal amplitude	9
6.5 Assessments of the measurement	10
7 Evaluation	11
7.1 Determination of absorption via photothermal measurement	11
7.2 Determination of absorptance via photothermal calibration	12
7.3 Two-dimensional/three-dimensional maps of absorption	13
7.4 Mapping area and spatial resolution	13
8 Test report	14
Annex A (informative) Theoretical and practical considerations on calibration	16
Annex B (informative) Separation of surface absorption and bulk absorption	18
Annex C (informative) Test report	21
Bibliography	22