

ISO 6760-2:2024-05 (E)

Optics and photonics - Test method for temperature coefficient of refractive index of optical glasses - Part 2: Interferometric method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Measuring apparatus	2
5.1	General	2
5.2	Light sources	3
5.3	Thermal chamber	4
5.4	Flat plates	4
5.5	Interferometer for optical path length change measurement	5
5.6	Interferometer for expansion measurement	5
5.7	Detectors	5
5.8	Temperature sensor	6
5.9	Barometer	6
6	Measurement specimen	6
7	Measurement procedure	6
8	Calculation	7
8.1	Temperature coefficient of absolute refractive index	7
8.2	Linear expansion coefficient of specimen	8
8.3	Temperature coefficient of relative refractive index	8
9	How to express the temperature coefficient of refractive index	9
10	Test report	10
Annex A (informative) Formula for calculating the refractive index of air		11
Annex B (normative) Calculation of absolute refractive index of specimen at a given temperature using the temperature coefficient of refractive index		13
Annex C (informative) Temperature coefficient of refractive index under continuous temperature change		17
Annex D (informative) Sensor specifications		19
Annex E (informative) How to find the deviation of interference fringes between two temperatures		21
Annex F (normative) Flat plate requirements		23
Annex G (normative) Heating rate and temperature distribution		25
Bibliography		26