

DIN ISO 9335:2026-09 (E)

Optics and photonics - Optical transfer function - Principles and procedures of measurement (ISO 9335:2025)

Contents

Page

Foreword.....	v
Introduction	vi
1 Scope.....	1
2 Normative references	1
3 Terms and definitions	1
4 Measuring equipment and environment	1
4.1 General aspects	1
4.1.1 Measuring conditions	1
4.1.2 Uncertainty of measurement	1
4.2 Environment	2
4.2.1 General	2
4.2.2 Temperature and humidity control	2
4.2.3 Vibration	2
4.2.4 Electromagnetic disturbances	2
4.3 Measuring equipment	2
4.3.1 Optical mounts	2
4.3.2 Defocusing tolerance	3
4.3.3 Provision of measuring scales	3
4.4 System components	3
4.4.1 General	3
4.4.2 Optical benches	3
4.4.3 Test target unit	4
4.4.4 Mounting of the test specimen	9
4.4.5 Image evaluation system	9
4.4.6 Auxiliary imaging systems	10
5 Measurement procedures	10
5.1 General	10
5.2 Setting the measuring conditions	10
5.2.1 General	10
5.2.2 Environmental conditions	10
5.2.3 Spectral characteristics	11
5.2.4 Angular distribution and aperture considerations	11
5.2.5 Image scale and magnification	11
5.2.6 Focusing	11
5.3 Additional considerations of measurement	12
5.3.1 General	12
5.3.2 Linear range of test specimen	12
5.3.3 Isoplanatic region	12
5.3.4 Fixed pattern noise	12
5.3.5 Analysed area	12
5.3.6 Background radiation	12
5.3.7 Veiling glare	13
5.3.8 Parallelism of image and analysing element	13
5.3.9 Signal-to-noise ratio	13
5.4 Particular measuring conditions	14
5.4.1 Azimuths	14
5.4.2 Selection of image heights or field angles	14
5.4.3 Reference angles of the test specimen	14

6	Corrections to measured data	14
6.1	Normalization	14
6.2	Correction of the frequency scale	14
6.3	Correction of the measured modulation	15
6.4	Auxiliary imaging systems	15
7	Presentation of OTF data	15
7.1	General	15
7.2	Statement of identification and measuring conditions	15
7.3	Graphical presentation of OTF data	16
7.4	Numerical presentation	17
8	Uncertainty checks	17
Annex A (informative) Examples of the presentation of OTF data		19
Bibliography		24