

ISO 14999-4:2026-05 (E)

Optics and photonics - Measurement of optical elements and optical systems - Part 4: Interpretation and evaluation of surface form and wavefront deformation tolerances specified in ISO 10110

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
3.1 Mathematical definitions	2
3.2 Definition of optical functions	2
3.3 Definition of Zernike polynomials	6
3.4 Definitions of functions and terms for tolerancing the slope and curvature deviation	6
3.5 Definitions of functions and terms for tolerancing the Zernike residual RMS	9
4 Decomposition of measured data	9
5 Relating interferometric measurements to surface form deviation or transmitted wavefront deformation	12
5.1 Test areas	12
5.2 Quantities	12
5.3 Single-pass transmitted wavefront deformation	12
5.4 Double-pass transmitted wavefront deformation for straight transmission measurements	12
5.5 Surface form deviation	12
5.6 Conversion to other wavelengths	12
5.7 Conversion of non-interferometric measurements to wavefront deformation	13
6 Representation of the measured wavefront deviation as Zernike coefficients	13
7 Measurement and tolerancing of the slope and curvature deviation	13
7.1 General	13
7.2 Quantities	14
7.3 One-dimensional measurement of the slope and curvature deviation	14
7.4 Two-dimensional measurement of the slope and curvature deviation	16
7.5 Detrending	17
8 Calculation procedure for the Zernike residual RMS	17
Annex A (normative) Estimation of peak-to-valley value (PV)	18
Annex B (normative) Zernike polynomials	22
Annex C (normative) Visual interferogram analysis	25
Bibliography	33