

ISO 11551:2026-08 (E)

Optics and photonics - Lasers and laser-related equipment - Test method for absorptance of optical laser components

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and units of measure	1
5 Preparation of test sample and measuring arrangement	2
6 Characteristic features of the laser radiation	4
7 Test procedure	5
7.1 General	5
7.2 Calibration	5
7.2.1 Calibration of the radiant power signal	5
7.2.2 Calibration of the temperature signal	5
7.2.3 Calibration of the thermal response	5
7.2.4 Measurement of the background signal	6
7.3 Determining the absorptance	6
8 Evaluation	6
8.1 General	6
8.2 Elimination of drift	7
8.3 Exponential method	7
8.4 Pulse method	8
9 Test report	9
Annex A (informative) Effects changing absorptance	11
Annex B (informative) Influence of signal distortions	14
Annex C (informative) Algorithm for parameterizing the temperature data	17
Bibliography	18