

# ISO 16063-32:2016-09 (E)

## Methods for the calibration of vibration and shock transducers - Part 32: Resonance testing - Testing the frequency and the phase response of accelerometers by means of shock excitation

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Factors influencing measurement reproducibility .....</b>	<b>1</b>
<b>4</b>	<b>Apparatus and other devices .....</b>	<b>2</b>
4.1	Environmental conditions .....	2
4.2	Reference shock ball .....	2
4.2.1	General .....	2
4.2.2	Reference shock ball dimensions .....	2
4.2.3	Options for the reference shock ball diameter range .....	2
4.2.4	Requirements for the mounting surface and the thread tolerances of a reference shock ball .....	4
4.3	Impact ball .....	4
4.4	Signal analyser .....	4
4.5	Conditioning amplifier .....	5
4.6	Auxiliary devices and means .....	5
<b>5</b>	<b>Procedure .....</b>	<b>6</b>
5.1	Assembling the structure under test .....	6
5.1.1	Mounting the accelerometer under test .....	6
5.1.2	Mounting a reference shock ball .....	6
5.1.3	Mounting the guidance tube for the impact ball .....	6
5.2	Connecting the instruments .....	7
5.3	Setting the signal analyser .....	7
5.3.1	Initializing the analyser .....	7
5.3.2	Specifying the measurement parameters .....	8
5.3.3	Configuring the display .....	8
5.3.4	Configuring the markers .....	8
5.4	Testing .....	8
<b>6</b>	<b>Processing the results .....</b>	<b>9</b>
6.1	Recording the time signal .....	9
6.2	Processing the time signal .....	9
<b>7</b>	<b>Reporting the results .....</b>	<b>10</b>
7.1	Reporting the measurement results .....	10