

ISO 11161:2007-05 (E)

Safety of machinery - Integrated manufacturing systems - Basic requirements

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Strategy for risk assessment and risk reduction	6
4.1	General	6
4.2	Specification of the limits of the IMS	6
4.3	Determination of the task	6
4.4	Identifying hazardous situations	8
4.5	Risk estimation and risk evaluation	8
4.6	Risk reduction	8
5	Risk assessment	10
5.1	Specifications of the IMS	10
5.2	Identification of hazards and hazardous situations	12
5.3	Risk estimation	13
5.4	Risk evaluation	14
6	Risk reduction	14
6.1	Protective measures	14
6.2	Validation of the protective measures	14
7	Task zone(s)	14
7.1	General	14
7.2	Determination	15
7.3	Design	15
7.4	Functional analysis	16
8	Safeguarding and span of control	16
8.1	Safeguarding of task zones	16
8.2	Span of control	17
8.3	Electrical equipment requirements	17
8.4	Modes	17
8.5	Safeguards	18
8.6	Protective measures when safeguards are suspended	18
8.7	Muting and blanking	20
8.8	Control	20
8.9	Reset of perimeter safeguarding devices	21
8.10	Start/restart	21
8.11	Emergency stop	22
8.12	Measures for the escape and rescue of trapped persons	22
9	Information for use	22
9.1	General	22
9.2	Marking	23

10	Validation of the design	23
10.1	Validation that the design meets the requirements	23
10.2	Validation of the protective measures	23
	Annex A (informative) Examples of integrated manufacturing systems (IMs)	24
	Annex B (informative) Flow of information between the integrator, user and suppliers	27
	Annex C (informative) Span of control examples within an IMS	28
	Annex D (informative) Temporary observation of the automatic process	32
	Bibliography	36